
Multi Press Station Assembly Guide





6-319




Be careful to assemble all components in the sequence they are presented. Finger tighten all hardware in this step unless otherwise noted.


STEP 1 Right Side Assembly

NOTE: The right side of the 6-319 will be assembled in Step 1. Step 2 covers the left side assembly.

- A. Connect Upright Frame (C) and Flat Plate (12) to Base Frame (A) using:
 Two 2 (M12x80 hex head bolt)
 Four 4 (M12 washer)
 Two 5 (M12 nylon nut)
- B. Connect Side Frame (B) to Upright Frame (C) and Base Frame (A) using:
 One 3 (M12x25 hex head bolt)
 Two 1 (M12x70 hex head bolt)
 Two 4 (M12 washer)
- C. Insert Convex End Cap (7) into Upright Frame (C).
- D. Insert Foot Cap (8) onto Side Frame (B).
- E. Carefully lay the completed Right Side Assembly on the floor.



Multi Press Station Assembly Guide






Be careful to assemble all components in the sequence they are presented. Finger tighten all hardware in this step unless otherwise noted.

STEP 2 Left Side Assembly


NOTE: The right side of the 6-319 will be assembled in Step 1. Step 2 covers the left side assembly.

- A. Connect Upright Frame (C) and Flat Plate (12) to Base Frame (A) using:
 Two 2 (M12x80 hex head bolt)
 Four 4 (M12 washer)
 Two 5 (M12 nylon nut)
- B. Connect Side Frame (B) to Upright Frame (C) and Base Frame (A) using:
 One 3 (M12x25 hex head bolt)
 Two 1 (M12x70 hex head bolt)
 Two 4 (M12 washer)
- C. Insert Convex End Cap (7) into Upright Frame (C).
- D. Insert Foot Cap (8) onto Side Frame (B).
- E. Carefully lay the completed Left Side Assembly on the floor.
- F. Proceed to Step 3 to complete the assembly of the 6-319.



HART

Multi Press Station Assembly Guide





Be careful to assemble all components in the sequence they are presented. Finger tighten all hardware in this step unless otherwise noted.

STEP 3

A. Connect the Right Side Assembly and the Left Side Assembly with Cross Support (D) and two Weight Horns (G) using:

Two 2 (M12x80 hex head bolt)

Four 4 (M12 washer)

Two 5 (M12 nylon nut)

B. Wrench tighten all hardware that has been previously finger tightened and.

C. Connect Weight Horns (G) and Flat Plate (12) to the Left Side Assembly using:

Two 2 (M12x80 hex head bolt)

Four 4 (M12 washer)

Two 5 (M12 nylon nut)

D. Connect Weight Horns (G) and Flat Plate (12) to the Right Side Assembly using:

Two 2 (M12x80 hex head bolt)

Four 4 (M12 washer)

Two 5 (M12 nylon nut)

E. Connect Right Lift Off Frame (J) to the Right Side Assembly using:

Three 6 (M12x75 hex head bolt)

Six 4 (M12 washer)

Three 5 (M12 nylon nut)


F. Connect Left Lift Off Frame (I) to the Left Side Assembly using:

Three 6 (M12x75 hex head bolt)

Six 4 (M12 washer)

Three 5 (M12 nylon nut)

- G. Wrench tighten all remaining hardware.
- H. Insert Rubber End Cap (13) into all Weight Horns (G).
- I. Attach Rubber Bar Catch (9) to Right Safety Bar (E) and Left Safety Bar (F).
- J. Attach two 45mm x 45mm Pad (10) to Right Safety Bar (E) and Left Safety Bar (F).
- K. Attach Pad 45mm x 70mm (11) to Right Safety Bar (E) and Left Safety Bar (F).
- L. Congratulations! The installation of your 6-319 is complete.




Multi Press Station Assembly Guide



Above shows Step 3 assembled and completed.

Step 3





Mainframe Parts List

Part#	Qty	Description	
Α	2	BASE FRAME	
В	2	SIDE FRAME	
С	2	UPRIGHT FRAME	
D	1	CROSS SUPPORT	
E	1	RIGHT SAFETY BAR	
F	1	LEFT SAFETY BAR	
G	4	WEIGHT HORNS	
I	1	RIGHT LIFT OFF FRAME	130mm x 6mm T x 1610mm L
J	1	LEFT LIFT OFF FRAME	130mm x 6mm T x 1610mm L

Part numbers are required when ordering parts.

6-319



Hardware List


Part#	Qty	Description	
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20	4 12 2 40 18 6 2 2 2 4 2 4 2 1 1 1 1 1	HEX HEAD BOLT HEX HEAD BOLT HEX HEAD BOLT M12x80 HEX HEAD BOLT WASHER NYLON NUT HEX HEAD BOLT CONVEX END CAP FOOT CAP RUBBER BAR CATCH PAD PAD FLAT PLATE RUBBER END CAP NUMBER STICKER RIGHT STICKER WARNING STICKER MAINTENANCE LABEL HART-SPORT LOGO M12x75 M12x7	(9211-084) (9212-018) (9310-042) (9440-067) (9440-068) (8312-091) (9211-074) (9440-053) (9440-054) (9440-105) (9440-103) (9440-229) (9440-230)
21	1	WEIGHT HORN WARNING STICKER	(9440-217)


Part numbers are required when ordering parts.

hartsport.com.au 6-319




Hardware (To Scale)









Hardware (To Scale)




Part# 4 M12 Washer Qty. 40







Exploded View Diagram





Exploded View Diagram

